

ERASURE REPORT



Company information

Licensed to:	Blancco Oy Ltd.	Business location:	Joensuu
Erasure provider:	Testing	Erasure person:	Blancco Tester
Business name:	Testing		

Operator information

mac:	00:01:02:dc:f0:e3	time:	12:42:00 PM
date:	Friday 27 January 2012		

Erasure results information

Disk	Model: SAMSUNG	Type: SV1021H	Serial: 0266J1FR466144
	Size: 172698624	Bus: IDE/ATA	Sectors: 337302
	Remapped sectors: 0		
Method:	U.S. Navy Staff Office Publication NAVSO P-5239-26		Duration: 01:27:11
Status:	Erased		
Information:	3 overwriting rounds performed		
Start time:	2012-01-27 12:41:38 (+0200)	End time:	2012-01-27 14:09:49 (+0200)

Disk	Model: SAMSUNG	Type: HD080HJ	Serial: 00KB205887000000
	Size: 130690560	Bus: IDE/ATA	Sectors: 255255
	Remapped sectors: 0		
Method:	U.S. Navy Staff Office Publication NAVSO P-5239-26		Duration: 00:32:02
Status:	Not erased		
Information:	User cancelled the erasure 1 overwriting rounds performed		
Start time:	2012-01-27 12:41:38 (+0200)	End time:	2012-01-27 13:13:40 (+0200)

Hardware information

Manufacturer:	Hewlett-Packard	Chassis type:	Desktop
Model:	HP d230 MT(DQ444A)	Serial:	CZC4101S2G
Version:	1.11		
Processor:	Intel(R) Celeron(R) CPU 2.20GHz, current speed:2200000000		
Memory bank:	528482304		
Total Memory:	504MB, Free memory banks:0		
Graphics card:	Intel Corporation 82845G/GL[Brookdale-G]/GE Chipset Integrated Graphics Device		

I hereby state that the data erasure has been carried out in accordance with the instructions given by the software provider.

DATA ERASURE EXECUTIVE

SUPERVISOR